

County of Santa Clara

Department of Environmental Health

Consumer Protection Division

1555 Berger Drive, Suite 300, San Jose, CA 95112-2716

Phone (408) 918-3400 Fax (408) 298-6261 www.ehinfo.org



OFFICIAL INSPECTION REPORT

Owner Name: AUREFLAM CORP
Facility Name: JAZEN TEA OAKRIDGE
Site Address: 925 BLOSSOM HILL RD, SAN JOSE, CA 95123
Program: PR0425338 - FOOD PREP / FOOD SVC OP 0-5 EMPLOYEES RC 2 - FP10

Facility ID: FA0283551
Inspection Date: 11/18/2017
Inspection Time: 17:45-18:00

Inspected By: RAYMOND CHUNG
Inspection Type: FOLLOW-UP INSPECTION
Consent to Inspect Granted By: GABRIEL GONZALES

Pictures Taken

Major Risk Factors and Interventions Violations:

Cited On: 11/16/2017

K06M - 8 Points - Inadequate handwash facilities: supplied or accessible - Applicable Section(s):113953, 113953.1, 113953.2, 114067(f)

Inspector Observations:

1. Soap dispenser at the hand sink was empty. [corrective action] Keep the soap dispenser stocked.

Note: A bottle of dish soap was available during time of inspection. Refill the soap dispenser with HAND SOAP by 11/17/2017.

Corrected on
11/18/2017

2. Sponges and other miscellaneous items were stored in the hand sink. [corrective action] Keep the hand sink clear so that it accessible for hand washing.

Cited On: 11/16/2017

K21M - 8 Points - Hot and cold water not available - Applicable Section(s):113953(c), 114099.2(b), 114163(a), 114189, 114192, 114192.1, 11419

Inspector Observations:

Water from the 3-compartment sink and the hand sink measured at 70F. Manager noted that there is hot water in the morning but not enough to sustain throughout the day. [corrective action] Provide adequate supply of hot water at minimum of 120F.

Corrected on
11/18/2017

Minor Risk Factors and Interventions Violations:

N/A

Good Retail Practices Violations:

Performance Based Inspection Questions:

N/A

Measured Observations:

N/A

Overall Comments:

Follow-up inspection from 11/16/2017. This facility was closed due to lack of hot water.

- The tankless water heater was replaced. Hot water at the 3-compartment sink and hand sink measured at > 120F.

- This inspection to be billed \$493.00

When required to determine compliance, a single reinspection will be conducted without additional charge. If subsequent reinspections are required, an hourly fee (minimum one hour) at the current rate approved by the Board of Supervisors will be assessed for each and every reinspection until the necessary changes or corrections are made. Unless otherwise noted by the inspector, all violations are to be corrected no later than **12/2/2017**. Any major change in menu or any change in ownership must have prior approval by this Department. This may require structural and/or equipment changes or remodeling to accommodate new operations.

OFFICIAL INSPECTION REPORT

Owner Name: AUREFLAM CORP
Facility Name: JAZEN TEA OAKRIDGE
Site Address: 925 BLOSSOM HILL RD, SAN JOSE, CA 95123
Program: PR0425338 - FOOD PREP / FOOD SVC OP 0-5 EMPLOYEES RC 2 - FP10

Facility ID: FA0283551
Inspection Date: 11/18/2017
Inspection Time: 17:45-18:00

Legend:

[COS] Corrected on Site
[CA] Corrective Action
[SA] Suitable Alternative
[PIC] Person in Charge



Received By: Gabriel Gonzales
Lead
Signed On: November 18, 2017